


Appendix 9C-15 Performance Curve DI-12 in a Sump
(Side Slope 3:1)



Source: VDOT Transportation Research Council publication "HYDRAULIC EFFICIENCY OF GRATE INLET", 1988